

C.L. "BUTCH" OTTER – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

November 1, 2007

Coral Holley, Administrator Creekside Care Center 525 16th Avenue East Jerome, ID 83338

License #: RC-365

Dear Mr. Holley:

On September 26, 2007, a Fire Life Safety Survey was conducted at Creekside Care Center. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level:

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

EM/li

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 5, 2007

Coral Holley, Administrator Creekside Care Center 525 16th Avenue East Jerome, ID 83338

Dear Mr. Holley:

On September 26, 2007, a Fire Life Safety Survey was conducted at Creekside Care Center. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by October 26, 2007.

FILE COPY

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/lj

Enclosure

PRINTED: 10/02/2007 FORM APPROVED

(X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 01 - ENTIRE BUILDING A. BUILDING B. WING_ 09/26/2007 13R365 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 222 6TH AVE WEST **CREEKSIDE CARE CENTER** JEROME, ID 83338 (X5) COMPLETE DATE SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) R 000 R 000 Initial Comments The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted onSeptember 26, 2007. The surveyor conducting the survey was: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety & Construction Program

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

Facility	Name		Physical Address	Phone Number		
		e Can Certu	222 Lets Acelled	324-	-4941	
Administrator Coral Diane Holley			City Jerome	ZIP Code	ZIP Code 83338	
Survey	Team Leader	لبر	Survey Type	Survey Date ,		
En mulle Fire Life Sofety					26/01	
	-CORE ISSU	ES	1			
ITEM #	RULE # 16.03.22		DESCRIPTION		DATE RESOLVED	BFS USE
1	400	(ile Safety! See	end exit signs ded not ille	iminate	10/12/07	
'		you test.			1	13.55
2	405.03	The fram Exert	replaced in the Ortran	c/11 - room.	10/12/0-	7
			100000000000000000000000000000000000000	"0" "7" "7" "" ""	10/12/0/	A 45
			-	,		
						
	<u> </u>					
		PW0100-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-				
						19.43 S
				***************************************		100 70
				***************************************		3.5
						1 - (2.6 m × 2.6 m) 2 - 4 - 4 - 7 (2.6 m)
	<u> </u>		,			1400000000 14000000
···		-	•		-	1.00
Respon	se Required Date	Signature of Facility Representative				
10/24/07		1.931 1 9K	rayo		Date Signed	
1	t *					